
**Lake Thunderbird TMDL Monitoring Plan Implementation:
Sample Year (SY) 2018- June Report**



SY2018 Monthly Report

Lake Thunderbird TMDL Monitoring Plan Implementation:

June 2018 Monitoring Report

Oklahoma Water Resources Board
Water Quality Programs Division
Monitoring and Assessment Section
3800 N. Classen, Oklahoma City, Oklahoma 73118
405-530-8800

Contact

Sarah Dexter, Project Leader, sarah.dexter@owrb.ok.gov
Jason Murphy, Project Supervisor, jason.murphy@owrb.ok.gov
Lance Phillips, Streams Program Manager, lance.phillips@owrb.ok.gov
Bill Cauthron, Monitoring Coordinator, bill.cauthron@owrb.ok.gov



TABLE OF CONTENTS

Table of Contents.....	3
List of Tables.....	3
List of Figures	3
Summary of June Water Quality Sampling	4
Results.....	4

LIST OF TABLES

TABLE 1 FIELD DATA FORM	5
TABLE 2 LABORATORY ANALYSIS SUMMARY	6
TABLE 3 QA/QC DATA	6
TABLE 4 STATION DISCHARGE SUMMARY	6

LIST OF FIGURES

FIGURE 1 MONITORING STATION MAP	4
FIGURE 2 DISCHARGE SUMMARY WC-1.....	7
FIGURE 3 DISCHARGE SUMMARY URC-2.....	8
FIGURE 4 DISCHARGE SUMMARY UDB-1	9
FIGURE 5 DISCHARGE SUMMARY TG-1.....	10
FIGURE 6 DISCHARGE SUMMARY TE-1.....	11
FIGURE 7 DISCHARGE SUMMARY LRC-1.....	12
FIGURE 8 DISCHARGE SUMMARY CC-1	13
FIGURE 9 DISCHARGE SUMMARY LDB-1	14
FIGURE 10 MONTHLY HYDROGRAPH TE-1	15
FIGURE 11 MONTHLY HYDROGRAPH TG-1	15
FIGURE 12 MONTHLY HYDROGRAPH UDB-1	16
FIGURE 13 MONTHLY HYDROGRAPH JB-1	16
FIGURE 14 MONTHLY HYDROGRAPH URC-2	17
FIGURE 15 MONTHLY HYDROGRAPH WC-1.....	17
FIGURE 16 MONTHLY HYDROGRAPH LDB-1	18
FIGURE 17 MONTHLY HYDROGRAPH LRC-1	18
FIGURE 18 JUNE MESONET DATA	19

SUMMARY OF JUNE WATER QUALITY SAMPLING

Sampling for June 2018 occurred on the fifth and was considered a base flow collection. Water samples were collected at all ten locations, and discharge was measured at seven locations. Mesonet data shows 0.05 inches of precipitation occurring on the fifth, no precipitation in the 72 hours prior to sampling, and 1.65 inches of precipitation in the 72 hours after the sampling event. One stormwater sample was collected via autosampler at LDB-1, as well as a discharge measurement on the twenty-fifth of June. Mesonet data shows 1.26 inches of precipitation occurring on the twenty-fifth, 2.63 inches of precipitation occurring in the 72 hours prior to sampling, and no precipitation occurring in the 72 hours after sampling. The total rainfall amount in Norman for the month of June was 6.55 inches. All water level gauges were operational for the month, with the exception of LT-1 and CC-1 as a result of road construction activity.

RESULTS




Figure 1 Monitoring Station Map

Field Data Form

Field Measurement Record
Reviewed By: _____ **JM** _____

Station	Date	Time	Field Crew	Temp C°	DO mg/L	SpC µS	pH	Turb (NTU)	Notes
cc-1	6/5/2018	9:20	SD	20.8	7.1	710.0	7.9	7.0	road construction activity, trees/brush on ds rew have been removed, road over culvert removed
lt-1	6/5/2018	8:15	SD	23.2	3.8	545.0	7.8	57.0	disconnected from us at culvert. Sampled in large pool on ds side
jb-1	6/5/2018	10:10	SD	21.3	1.8	994.0	7.6	4.0	
udb-1	6/5/2018	10:30	SD	21.4	6.8	849.0	8.0	71.0	looks about base flow conditions, but water is turbid
ldb-1	6/5/2018	11:35	SD	25.6	5.4	686.0	8.0	50.0	no visible surface flow
tg-1	6/5/2018	15:30	SD	27.3	10.8	705.0	8.2	12.0	
te-1	6/5/2018	14:50	SD	26.0	9.4	928.0	7.8	9.0	
wc-1	6/5/2018	14:10	SD	25.7	9.3	862.0	7.7	37.0	
lrc-1	6/5/2018	12:20	SD	24.7	5.9	703.0	7.7	25.0	orifice completely out of water
urc-2	6/5/2018	13:05	SD	23.2	4.6	675.0	7.4	14.0	
ldb-1	6/25/2018	4:15	SD	N/A	N/A	256.0	7.8	497.0	Autosampler collected T1 at 18.017. After flow td=17.995

Table 1 Field Data Form

Site Name	TKN (mg/L)	Nitrate/Nitrite (mg/L)	TP (mg/L)	TSS (mg/L)
TG-1	0.41	0.06	0.048	13.0
CC-1	0.44	0.34	0.093	<5.0
JB-1	0.60	<0.05	0.110	6.0
UDB-1	0.51	0.15	0.091	56.0
LDB-1	0.94	<0.05	0.103	44.0
LRC-1	0.48	<0.05	0.070	25.0
URC-2	1.14	<0.05	0.114	14.0
WC-1	0.35	<0.05	0.069	9.0
TE-1	3.84	<0.05	0.030	9.0
LT-1	1.10	<0.05	0.080	58.0
LDB-1 (6/25/18)	1.59	0.27	0.315	265

Table 2 Laboratory Analysis Summary

Site Name	TKN	Nitrate/Nitrite	TP	TSS
Field Blank	<0.10 mg/L	<0.05 mg/L	<0.010 mg/L	<5.0 mg/L
Duplicate	0.44 mg/L	0.33 mg/L	0.093 mg/L	5.0 mg/L
Duplicate RPD	0%	0.44%	0%	0%

Table 3 QA/QC Data

Quality assurance/quality control (QA/QC) of the data includes a field blank and duplicate sample from each collection event, and is qualified by the OWRB. Relative Percent Difference (RPD) of the duplicate sample can be categorized into four levels, where Level 1 likely has no QA issues and Level 4 has major QA issues, and should be used with caution.

SITE	TG-1	CC-1	JB-1	UDB-1	LDB-1	LRC-1	URC-2	WC-1	TE-1	LT-1	LDB-1 (6/25/18)
STAGE (ft)	9.24	0.68	16.58	17.63	16.75	17.25	11.55	8.42	11.53	N/A	18.03
DISCHARGE (ft ³ /s)	2.35	0.36	0	1.61	0	0.12	0	0.02	0	0	80.08

Table 4 Station Discharge Summary

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name	WC0605.WAD
Start Date and Time	2018/06/05 11:18:22

Site Details

Site Name	WC
Operator(s)	JW

System Information

Sensor Type	FlowTracker
Serial #	P4709
CPU Firmware Version	3.9
Software Ver	2.30
Mounting Correction	0.0%

Units (English Units)

Distance	ft
Velocity	ft/s
Area	ft^2
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	1.8%	11.6%
Velocity	27.0%	135.6%
Width	0.8%	0.8%
Method	11.6%	-
# Stations	4.2%	-
Overall	29.8%	136.1%

Summary

Averaging Int.	40	# Stations	12
Start Edge	LEW	Total Width	12.000
Mean SNR	38.8 dB	Total Area	6.400
Mean Temp	79.63 °F	Mean Depth	0.533
Disch. Equation	Mid-Section	Mean Velocity	0.0030
		Total Discharge	0.0193

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 11:07:51 CDT 2018	0.000	8.420		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	11:18	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	<i>11:18</i>	<i>1.50</i>	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>-0.0003</i>	<i>1.00</i>	<i>-0.0003</i>	<i>0.300</i>	<i>-0.0001</i>	<i>-0.5</i>
2	<i>11:19</i>	<i>2.00</i>	<i>0.6</i>	<i>0.400</i>	<i>0.6</i>	<i>0.160</i>	<i>-0.0128</i>	<i>1.00</i>	<i>-0.0128</i>	<i>0.300</i>	<i>-0.0038</i>	<i>-19.9</i>
3	<i>11:20</i>	<i>3.00</i>	<i>0.6</i>	<i>0.500</i>	<i>0.6</i>	<i>0.200</i>	<i>0.0125</i>	<i>1.00</i>	<i>0.0125</i>	<i>0.500</i>	<i>0.0062</i>	<i>32.3</i>
4	<i>11:22</i>	<i>4.00</i>	<i>0.6</i>	<i>0.400</i>	<i>0.6</i>	<i>0.160</i>	<i>0.0180</i>	<i>1.00</i>	<i>0.0180</i>	<i>0.400</i>	<i>0.0072</i>	<i>37.3</i>
5	<i>11:23</i>	<i>5.00</i>	<i>0.6</i>	<i>0.400</i>	<i>0.6</i>	<i>0.160</i>	<i>0.0131</i>	<i>1.00</i>	<i>0.0131</i>	<i>0.400</i>	<i>0.0052</i>	<i>27.2</i>
6	<i>11:24</i>	<i>6.00</i>	<i>0.6</i>	<i>0.500</i>	<i>0.6</i>	<i>0.200</i>	<i>0.0066</i>	<i>1.00</i>	<i>0.0066</i>	<i>0.500</i>	<i>0.0033</i>	<i>17.0</i>
7	<i>11:25</i>	<i>7.00</i>	<i>0.6</i>	<i>0.700</i>	<i>0.6</i>	<i>0.280</i>	<i>0.0184</i>	<i>1.00</i>	<i>0.0184</i>	<i>0.700</i>	<i>0.0129</i>	<i>66.6</i>
8	<i>11:26</i>	<i>8.00</i>	<i>0.6</i>	<i>0.800</i>	<i>0.6</i>	<i>0.320</i>	<i>0.0161</i>	<i>1.00</i>	<i>0.0161</i>	<i>0.800</i>	<i>0.0129</i>	<i>66.5</i>
9	<i>11:27</i>	<i>9.00</i>	<i>0.6</i>	<i>1.000</i>	<i>0.6</i>	<i>0.400</i>	<i>-0.0200</i>	<i>1.00</i>	<i>-0.0200</i>	<i>1.000</i>	<i>-0.0200</i>	<i>-103.6</i>
10	<i>11:28</i>	<i>10.00</i>	<i>0.6</i>	<i>1.000</i>	<i>0.6</i>	<i>0.400</i>	<i>-0.0030</i>	<i>1.00</i>	<i>-0.0030</i>	<i>1.500</i>	<i>-0.0044</i>	<i>-22.9</i>
11	<i>11:28</i>	<i>12.00</i>	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 2 Discharge Summary WC-1

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name	URC0605.WAD
Start Date and Time	2018/06/05 10:13:23

Site Details

Site Name	URC
Operator(s)	JW

System Information

Sensor Type	FlowTracker
Serial #	P4709
CPU Firmware Version	3.9
Software Ver	2.30
Mounting Correction	0.0%

Units	(English Units)
Distance	ft
Velocity	ft/s
Area	ft^2
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	3.9%	80.7%
Velocity	65.6%	289.2%
Width	1.6%	1.6%
Method	24.3%	-
# Stations	6.6%	-
Overall	70.4%	300.2%

Summary

Averaging Int.	40	# Stations	8
Start Edge	LEW	Total Width	8.000
Mean SNR	46.8 dB	Total Area	5.350
Mean Temp	78.52 °F	Mean Depth	0.669
Disch. Equation	Mid-Section	Mean Velocity	-0.0012
		Total Discharge	-0.0063

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	10:13	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	<i>10:14</i>	<i>1.00</i>	<i>0.6</i>	<i>0.600</i>	<i>0.6</i>	<i>0.240</i>	<i>-0.0007</i>	<i>1.00</i>	<i>-0.0007</i>	<i>0.600</i>	<i>-0.0004</i>	<i>6.3</i>
2	10:16	2.00	0.6	0.900	0.6	0.360	-0.0043	1.00	-0.0043	0.900	-0.0038	61.0
3	10:13	3.00	0.6	0.800	0.6	0.320	-0.0184	1.00	-0.0184	0.800	-0.0147	233.4
4	10:18	4.00	0.6	0.600	0.6	0.240	-0.0059	1.00	-0.0059	0.600	-0.0035	56.3
5	10:19	5.00	0.6	1.100	0.6	0.440	0.0115	1.00	0.0115	1.100	0.0126	-200.6
6	10:20	6.00	0.6	0.900	0.6	0.360	0.0026	1.00	0.0026	1.350	0.0035	-56.3
7	10:20	8.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 3 Discharge Summary URC-2

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name UDB0605.WAD
Start Date and Time 2018/06/05 07:54:45

Site Details

Site Name UDB
Operator(s) JW

System Information

Sensor Type FlowTracker
Serial # P4709
CPU Firmware Version 3.9
Software Ver 2.30
Mounting Correction 0.0%

Units (English Units)

Distance	ft
Velocity	ft/s
Area	ft ²
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	0.4%	3.6%
Velocity	0.9%	5.1%
Width	0.1%	0.1%
Method	1.8%	-
# Stations	2.4%	-
Overall	3.3%	6.3%

Summary

Averaging Int.	40	# Stations	21
Start Edge	LEW	Total Width	11.000
Mean SNR	35.7 dB	Total Area	6.550
Mean Temp	70.07 °F	Mean Depth	0.595
Disch. Equation	Mid-Section	Mean Velocity	0.2464
		Total Discharge	1.6136

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 08:20:13 CDT 2018	11.000	17.630		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	07:54	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	07:54	1.00	0.6	0.700	0.6	0.280	0.3182	1.00	0.3182	0.525	0.1671	10.4
2	07:55	1.50	0.6	0.900	0.6	0.360	0.2080	1.00	0.2080	0.450	0.0936	5.8
3	07:57	2.00	0.6	0.900	0.6	0.360	0.1824	1.00	0.1824	0.450	0.0821	5.1
4	07:58	2.50	0.6	0.900	0.6	0.360	0.2257	1.00	0.2257	0.450	0.1016	6.3
5	07:59	3.00	0.6	0.900	0.6	0.360	0.0728	1.00	0.0728	0.450	0.0328	2.0
6	08:00	3.50	0.6	0.900	0.6	0.360	0.3028	1.00	0.3028	0.450	0.1363	8.4
7	08:01	4.00	0.6	0.700	0.6	0.280	0.2986	1.00	0.2986	0.350	0.1045	6.5
8	08:02	4.50	0.6	0.800	0.6	0.320	0.3156	1.00	0.3156	0.400	0.1262	7.8
9	08:03	5.00	0.6	0.600	0.6	0.240	0.3261	1.00	0.3261	0.300	0.0978	6.1
10	08:04	5.50	0.6	0.400	0.6	0.160	0.3251	1.00	0.3251	0.200	0.0650	4.0
11	08:05	6.00	0.6	0.400	0.6	0.160	0.2979	1.00	0.2979	0.200	0.0596	3.7
12	08:06	6.50	0.6	0.400	0.6	0.160	0.3041	1.00	0.3041	0.200	0.0608	3.8
13	08:07	7.00	0.6	0.500	0.6	0.200	0.2877	1.00	0.2877	0.250	0.0719	4.5
14	08:08	7.50	0.6	0.400	0.6	0.160	0.2979	1.00	0.2979	0.200	0.0596	3.7
15	08:09	8.00	0.6	0.800	0.6	0.320	0.2198	1.00	0.2198	0.400	0.0879	5.4
16	08:10	8.50	0.6	0.800	0.6	0.320	0.1900	1.00	0.1900	0.400	0.0760	4.7
17	08:11	9.00	0.6	0.800	0.6	0.320	0.1709	1.00	0.1709	0.400	0.0684	4.2
18	08:12	9.50	0.6	0.500	0.6	0.200	0.2031	1.00	0.2031	0.250	0.0508	3.1
19	08:13	10.00	0.6	0.300	0.6	0.120	0.3189	1.00	0.3189	0.225	0.0717	4.4
20	08:13	11.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 4 Discharge Summary UDB-1

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name TG605.WAD
Start Date and Time 2018/06/05 12:44:36

Site Details

Site Name LITTLE RIV TG
Operator(s) JW

System Information

Sensor Type FlowTracker
Serial # P4709
CPU Firmware Version 3.9
Software Ver 2.30
Mounting Correction 0.0%

Units (English Units)
Distance ft
Velocity ft/s
Area ft²
Discharge cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	0.3%	1.6%
Velocity	0.5%	1.3%
Width	0.1%	0.1%
Method	1.7%	-
# Stations	2.0%	-
Overall	2.9%	2.3%

Summary

Averaging Int.	40	# Stations	25
Start Edge	LEW	Total Width	15.000
Mean SNR	27.2 dB	Total Area	7.900
Mean Temp	80.66 °F	Mean Depth	0.527
Disch. Equation	Mid-Section	Mean Velocity	0.2977
		Total Discharge	2.3517

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 12:47:33 CDT 2018	4.500	9.240		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	12:44	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	12:45	1.50	0.6	0.400	0.6	0.160	0.2270	1.00	0.2270	0.400	0.0908	3.9
2	12:46	2.00	0.6	0.500	0.6	0.200	0.2795	1.00	0.2795	0.250	0.0699	3.0
3	12:47	2.50	0.6	0.500	0.6	0.200	0.3415	1.00	0.3415	0.250	0.0854	3.6
4	12:48	3.00	0.6	0.500	0.6	0.200	0.3015	1.00	0.3015	0.250	0.0754	3.2
5	12:50	3.50	0.6	0.700	0.6	0.280	0.2743	1.00	0.2743	0.350	0.0960	4.1
6	12:51	4.00	0.6	0.800	0.6	0.320	0.3448	1.00	0.3448	0.400	0.1379	5.9
7	12:52	4.50	0.6	0.800	0.6	0.320	0.3855	1.00	0.3855	0.400	0.1542	6.6
8	12:53	5.00	0.6	0.700	0.6	0.280	0.4364	1.00	0.4364	0.350	0.1528	6.5
9	12:53	5.50	0.6	0.900	0.6	0.360	0.3983	1.00	0.3983	0.450	0.1792	7.6
10	12:54	6.00	0.6	0.900	0.6	0.360	0.3537	1.00	0.3537	0.450	0.1591	6.8
11	12:56	6.50	0.6	0.900	0.6	0.360	0.3638	1.00	0.3638	0.450	0.1637	7.0
12	12:57	7.00	0.6	0.800	0.6	0.320	0.3596	1.00	0.3596	0.400	0.1438	6.1
13	12:57	7.50	0.6	0.800	0.6	0.320	0.3294	1.00	0.3294	0.400	0.1317	5.6
14	12:58	8.00	0.6	0.800	0.6	0.320	0.3054	1.00	0.3054	0.400	0.1222	5.2
15	12:59	8.50	0.6	0.700	0.6	0.280	0.3094	1.00	0.3094	0.350	0.1083	4.6
16	13:00	9.00	0.6	0.700	0.6	0.280	0.2746	1.00	0.2746	0.350	0.0961	4.1
17	13:01	9.50	0.6	0.700	0.6	0.280	0.2441	1.00	0.2441	0.350	0.0854	3.6
18	13:02	10.00	0.6	0.600	0.6	0.240	0.2470	1.00	0.2470	0.300	0.0741	3.2
19	13:03	10.50	0.6	0.500	0.6	0.200	0.2080	1.00	0.2080	0.250	0.0520	2.2
20	13:04	11.00	0.6	0.500	0.6	0.200	0.1929	1.00	0.1929	0.250	0.0482	2.1
21	13:05	11.50	0.6	0.400	0.6	0.160	0.2018	1.00	0.2018	0.200	0.0403	1.7
22	13:06	12.00	0.6	0.400	0.6	0.160	0.1811	1.00	0.1811	0.200	0.0362	1.5
23	13:06	12.50	0.6	0.300	0.6	0.120	0.1086	1.00	0.1086	0.450	0.0488	2.1
24	13:06	15.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 5 Discharge Summary TG-1

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name TE0605.WAD
Start Date and Time 2018/06/05 12:04:24

Site Details

Site Name TE
Operator(s) JW

System Information

Sensor Type FlowTracker
Serial # P4709
CPU Firmware Version 3.9
Software Ver 2.30
Mounting Correction 0.0%

Units (English Units)

Distance	ft
Velocity	ft/s
Area	ft ²
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	2.9%	30.9%
Velocity	42.9%	181.5%
Width	1.0%	1.0%
Method	14.7%	-
# Stations	5.8%	-
Overall	45.8%	184.1%

Summary

Averaging Int.	40	# Stations	9
Start Edge	LEW	Total Width	8.000
Mean SNR	46.0 dB	Total Area	5.300
Mean Temp	80.28 °F	Mean Depth	0.662
Disch. Equation	Mid-Section	Mean Velocity	-0.0025
		Total Discharge	-0.0132

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 12:09:30 CDT 2018	5.000	11.530		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	12:04	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	<i>12:04</i>	<i>1.00</i>	<i>0.6</i>	<i>0.400</i>	<i>0.6</i>	<i>0.160</i>	<i>-0.0292</i>	<i>1.00</i>	<i>-0.0292</i>	<i>0.400</i>	<i>-0.0117</i>	<i>88.6</i>
2	12:05	2.00	0.6	0.900	0.6	0.360	-0.0157	1.00	-0.0157	0.900	-0.0142	107.5
3	12:07	3.00	0.6	0.900	0.6	0.360	0.0092	1.00	0.0092	0.900	0.0083	-62.7
4	12:08	4.00	0.6	0.900	0.6	0.360	0.0059	1.00	0.0059	0.900	0.0053	-40.3
5	12:09	5.00	0.6	0.800	0.6	0.320	0.0092	1.00	0.0092	0.800	0.0073	-55.7
6	12:10	6.00	0.6	0.800	0.6	0.320	-0.0157	1.00	-0.0157	0.800	-0.0126	95.5
7	12:11	7.00	0.6	0.600	0.6	0.240	0.0072	1.00	0.0072	0.600	0.0043	-32.8
8	12:11	8.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 6 Discharge Summary TE-1

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name	LRC0605.WAD
Start Date and Time	2018/06/05 09:27:38

Site Details

Site Name	LRC
Operator(s)	JW

System Information

Sensor Type	FlowTracker
Serial #	P4709
CPU Firmware Version	3.9
Software Ver	2.30
Mounting Correction	0.0%

Units	(English Units)
Distance	ft
Velocity	ft/s
Area	ft^2
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	0.5%	3.7%
Velocity	8.3%	58.3%
Width	0.3%	0.3%
Method	3.8%	-
# Stations	3.1%	-
Overall	9.8%	58.4%

Summary

Averaging Int.	40	# Stations	16
Start Edge	LEW	Total Width	15.000
Mean SNR	46.0 dB	Total Area	14.500
Mean Temp	76.18 °F	Mean Depth	0.967
Disch. Equation	Mid-Section	Mean Velocity	0.0085
		Total Discharge	0.1228

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 09:44:43 CDT 2018	15.000	17.250		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	09:27	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	<i>09:27</i>	<i>1.00</i>	<i>0.6</i>	<i>0.400</i>	<i>0.6</i>	<i>0.160</i>	<i>0.0164</i>	<i>1.00</i>	<i>0.0164</i>	<i>0.400</i>	<i>0.0066</i>	<i>5.3</i>
2	<i>09:30</i>	<i>2.00</i>	<i>0.6</i>	<i>0.800</i>	<i>0.6</i>	<i>0.320</i>	<i>0.0246</i>	<i>1.00</i>	<i>0.0246</i>	<i>0.800</i>	<i>0.0197</i>	<i>16.0</i>
3	<i>09:29</i>	<i>3.00</i>	<i>0.6</i>	<i>1.000</i>	<i>0.6</i>	<i>0.400</i>	<i>0.0184</i>	<i>1.00</i>	<i>0.0184</i>	<i>1.000</i>	<i>0.0184</i>	<i>15.0</i>
4	<i>09:31</i>	<i>4.00</i>	<i>0.6</i>	<i>1.100</i>	<i>0.6</i>	<i>0.440</i>	<i>0.0135</i>	<i>1.00</i>	<i>0.0135</i>	<i>1.100</i>	<i>0.0148</i>	<i>12.1</i>
5	09:33	5.00	0.6	1.400	0.6	0.560	0.0105	1.00	0.0105	1.400	0.0147	12.0
6	09:34	6.00	0.6	1.600	0.6	0.640	-0.0079	1.00	-0.0079	1.600	-0.0126	-10.3
7	09:35	7.00	0.6	1.500	0.6	0.600	0.0226	1.00	0.0226	1.500	0.0340	27.7
8	09:36	8.00	0.6	1.400	0.6	0.560	-0.0023	1.00	-0.0023	1.400	-0.0032	-2.6
9	09:37	9.00	0.6	1.200	0.6	0.480	0.0194	1.00	0.0194	1.200	0.0232	18.9
10	09:38	10.00	0.6	1.100	0.6	0.440	-0.0010	1.00	-0.0010	1.100	-0.0011	-0.9
11	09:39	11.00	0.6	0.800	0.6	0.320	0.0095	1.00	0.0095	0.800	0.0076	6.2
12	<i>09:40</i>	<i>12.00</i>	<i>0.6</i>	<i>0.800</i>	<i>0.6</i>	<i>0.320</i>	<i>0.0226</i>	<i>1.00</i>	<i>0.0226</i>	<i>0.800</i>	<i>0.0181</i>	<i>14.7</i>
13	<i>09:41</i>	<i>13.00</i>	<i>0.6</i>	<i>0.800</i>	<i>0.6</i>	<i>0.320</i>	<i>-0.0276</i>	<i>1.00</i>	<i>-0.0276</i>	<i>0.800</i>	<i>-0.0220</i>	<i>-18.0</i>
14	<i>09:43</i>	<i>14.00</i>	<i>0.6</i>	<i>0.600</i>	<i>0.6</i>	<i>0.240</i>	<i>0.0079</i>	<i>1.00</i>	<i>0.0079</i>	<i>0.600</i>	<i>0.0047</i>	<i>3.8</i>
15	09:43	15.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 7 Discharge Summary LRC-1

Discharge Measurement Summary

Date Generated: Wed Jun 6 2018

File Information

File Name	CC0605.WAD
Start Date and Time	2018/06/05 06:43:30

Site Details

Site Name	C C
Operator(s)	JW

System Information

Sensor Type	FlowTracker
Serial #	P4709
CPU Firmware Version	3.9
Software Ver	2.30
Mounting Correction	0.0%

Units	(English Units)
Distance	ft
Velocity	ft/s
Area	ft^2
Discharge	cfs

Discharge Uncertainty

Category	ISO	Stats
Accuracy	1.0%	1.0%
Depth	0.5%	2.3%
Velocity	2.5%	17.1%
Width	0.2%	0.2%
Method	2.7%	-
# Stations	3.1%	-
Overall	5.0%	17.2%

Summary

Averaging Int.	40	# Stations	16
Start Edge	LEW	Total Width	9.000
Mean SNR	34.1 dB	Total Area	3.024
Mean Temp	68.92 °F	Mean Depth	0.336
Disch. Equation	Mid-Section	Mean Velocity	0.1195
		Total Discharge	0.3615

Supplemental Data

#	Time	Location	Gauge Height	Rated Flow	Comments
1	Tue Jun 5 07:01:18 CDT 2018	9.000	0.680		

Measurement Results

St	Clock	Loc	Method	Depth	%Dep	MeasD	Vel	CorrFact	MeanV	Area	Flow	%Q
0	06:43	0.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0
1	<i>06:43</i>	1.00	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>-0.0082</i>	<i>1.00</i>	<i>-0.0082</i>	<i>0.225</i>	<i>-0.0018</i>	<i>-0.5</i>
2	06:44	1.50	0.6	0.300	0.6	0.120	0.0046	1.00	0.0046	0.150	0.0007	0.2
3	<i>06:45</i>	2.00	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>0.0686</i>	<i>1.00</i>	<i>0.0686</i>	<i>0.150</i>	<i>0.0103</i>	<i>2.8</i>
4	06:46	2.50	0.6	0.300	0.6	0.120	0.1834	1.00	0.1834	0.150	0.0275	7.6
5	<i>06:47</i>	3.00	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>0.2628</i>	<i>1.00</i>	<i>0.2628</i>	<i>0.150</i>	<i>0.0394</i>	<i>10.9</i>
6	06:48	3.50	0.6	0.300	0.6	0.120	0.1703	1.00	0.1703	0.150	0.0255	7.1
7	<i>06:49</i>	4.00	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>0.1614</i>	<i>1.00</i>	<i>0.1614</i>	<i>0.150</i>	<i>0.0242</i>	<i>6.7</i>
8	06:50	4.50	0.6	0.300	0.6	0.120	0.2339	1.00	0.2339	0.150	0.0351	9.7
9	<i>06:50</i>	5.00	<i>0.6</i>	<i>0.300</i>	<i>0.6</i>	<i>0.120</i>	<i>0.1388</i>	<i>1.00</i>	<i>0.1388</i>	<i>0.150</i>	<i>0.0208</i>	<i>5.8</i>
10	06:51	5.50	0.6	0.400	0.6	0.160	0.3704	1.00	0.3704	0.200	0.0741	20.5
11	06:52	6.00	0.6	0.500	0.6	0.200	0.3094	1.00	0.3094	0.250	0.0773	21.4
12	06:53	6.50	0.6	0.500	0.6	0.200	0.0886	1.00	0.0886	0.250	0.0221	6.1
13	06:54	7.00	0.6	0.600	0.6	0.240	-0.0033	1.00	-0.0033	0.300	-0.0010	-0.3
14	06:56	7.50	0.6	0.600	0.6	0.240	0.0121	1.00	0.0121	0.600	0.0073	2.0
15	06:56	9.00	None	0.000	0.0	0.0	0.0000	1.00	0.0000	0.000	0.0000	0.0

Rows in italics indicate a QC warning. See the Quality Control page of this report for more information.

Figure 8 Discharge Summary CC-1

Station Number:
Station Name: lowerdaveblue

Meas. No: 1
Date: 06/25/2018

Party: sd lo	Width: 46.5 ft	Processed by:
Boat/Motor:	Area: 172 ft ²	Mean Velocity: 0.465 ft/s
Gage Height: 18.03 ft	G.H.Change: 0.000 ft	Discharge: 80.1 ft ³ /s
Area Method: Avg. Course	ADCP Depth: 0.270 ft	Index Vel.: 0.00 ft/s Rating No.: 1
Nav. Method: Bottom Track	Shore Ens.:10	Adj.Mean Vel: 0.00 ft/s Qm Rating: U
MagVar Method: None (0.0°)	Bottom Est: Power (0.1667)	Rated Area: 0.000 ft ² Diff.: 0.000%
Depth: Composite (BT)	Top Est: Power (0.1667)	Control1: Unspecified
Discharge Method: None		Control2: Unspecified
% Correction: 0.00		Control3: Unspecified
Screening Thresholds:		ADCP:
BT 3-Beam Solution: YES	Max. Vel.: 10.7 ft/s	Type/Freq.: RiverRay / 0 kHz
WT 3-Beam Solution: YES	Max. Depth: 6.13 ft	Serial #: 645650 Firmware: 44.16
BT Error Vel.: 3.28 ft/s	Mean Depth: 3.71 ft	Bin Size: 50 cm Blank: 50 cm
WT Error Vel.: 32.81 ft/s	% Meas.: 49.91	BT Mode: 0 BT Pings: 1
BT Up Vel.: 32.81 ft/s	Water Temp.: None	WT Mode: 1 WT Pings: 1
WT Up Vel.: 32.81 ft/s	ADCP Temp.: 71.5 °F	WV : 170
Use Weighted Mean Depth: YES		

Performed Diag. Test: NO

Project Name: lowerdave0625_1.mmt

Performed Moving Bed Test: NO



Software: 2.17

Performed Compass Calibration: NO Evaluation: NO

Meas. Location:

Tr.#	Edge Distance		#Ens.	Discharge						Width	Area	Time		Mean Vel.		% Bad		
	L	R		Top	Middle	Bottom	Left	Right	Total			Start	End	Boat	Water	Ens.	Bins	
000	R	3	3	125	17.9	42.4	17.2	-0.177	1.52	78.8	47	179	14:43	14:45	0.61	0.44	40	0
001	L	3	3	95	19.0	37.3	18.6	0.494	2.58	77.9	49	173	14:45	14:46	0.72	0.45	42	0
003	L	3	3	94	17.3	39.8	18.1	0.141	1.20	76.5	44	168	14:47	14:48	0.73	0.46	34	0
005	L	3	3	79	20.0	41.0	18.9	0.671	1.94	82.5	44	167	14:49	14:50	0.83	0.50	39	0
007	L	3	3	95	23.2	39.3	19.2	1.52	1.38	84.6	49	176	14:52	14:53	0.68	0.48	39	1
Mean	3	3	97	19.5	40.0	18.4	0.530	1.72	80.1	47	172	Total	00:09	0.71	0.46	39	0	
SDev	0	0	17	2.31	1.90	0.796	0.642	0.551	3.38	2.5	5.3			0.08	0.02			
SD/M	0.00	0.00	0.17	0.12	0.05	0.04	1.21	0.32	0.04	0.05	0.03			0.11	0.05			

Figure 9 Discharge Summary LDB-1






Figure 12 Monthly Hydrograph UDB-1




Figure 13 Monthly Hydrograph JB-1




Figure 14 Monthly Hydrograph URC-2




Figure 15 Monthly Hydrograph WC-1




Figure 16 Monthly Hydrograph LDB-1




Figure 17 Monthly Hydrograph LRC-1

MESONET CLIMATOLOGICAL DATA SUMMARY (NRMN) Norman Latitude: 35-14-09								June 2018 Nearest City: 2.1 NW Norman Longitude: 97-27-53						Time Zone: Midnight-Midnight CST County: Cleveland Elevation: 1171 feet						
DAY	TEMPERATURE (°F)				DEG DAYS		HUMIDITY (%)			RAIN (in)	PRESSURE (in)		WIND SPEED (mph)	SOLAR (MJ/m²)	4" SOIL TEMPERATURES					
	MAX	MIN	Avg	Dewpt	HDD	CDD	Max	Min	Avg		STN	MSL			SOD	BARE	MAX	MIN		
1	95	76	84.9	72.9	0	20	85	51	68	0.00	28.57	29.81	SSE	9.7	24.2	28.12	80.6	87.2	95	80
2	93	72	83.0	69.3	0	18	82	48	64	0.00	28.65	29.89	NNE	11.5	31.3	27.50	81.2	87.5	94	81
3	84	63	74.3	55.4	0	9	77	35	54	0.00	28.89	30.14	NE	7.6	29.1	30.11	78.9	84.3	92	77
4	83	58	72.5	61.5	0	6	90	53	69	0.00	28.78	30.03	SE	7.6	21.3	19.96	76.9	81.0	87	75
5	89*	66*	77.6*	68.2*	0*	12*	93*	56*	74*	0.05*	28.63*	29.88*	SE *	8.0*	20.6*	NA	78.3*	82.6*	91*	75*
6	93	73	82.3	72.3	0	18	91	52	73	0.00	28.61	29.86	SE	9.1	24.1	27.29	80.5	86.0	94	79
7	79	65	72.4	67.4	0	7	99	66	85	1.65	28.70	29.94	SE	9.9	29.0	4.28	76.4	79.0	86	74
8	88	64	77.6	68.2	0	11	98	53	75	0.00	28.76	30.01	SSE	6.0	18.5	23.39	76.3	77.0	83	71
9	91	71	81.9	67.9	0	16	90	48	64	0.00	28.73	29.98	SSE	9.5	24.6	28.39	79.1	78.4	84	73
10	92	72	82.3	70.0	0	17	79	55	67	0.00	28.59	29.83	SSE	10.1	23.6	27.85	80.0	80.4	89	73
11	91	75	83.6	72.2	0	18	82	58	69	0.00	28.53	29.77	SSE	10.3	23.5	27.86	81.1	84.9	93	77
12	86	70	77.7	69.4	0	13	96	57	76	0.17	28.66	29.91	S	9.1	37.5	13.48	79.6	80.7	85	77
13	93	73	83.2	71.6	0	18	96	49	70	0.00	28.72	29.97	SSE	7.4	17.8	27.68	80.4	83.0	93	75
14	93	74	84.1	66.5	0	19	75	39	57	0.00	28.69	29.94	S	9.6	23.2	27.46	81.1	85.9	94	78
15	92	75	83.9	67.6	0	19	74	44	59	0.00	28.64	29.89	SSE	10.5	27.1	28.62	81.2	87.1	95	80
16	90	75	82.8	68.7	0	18	78	53	63	0.00	28.64	29.89	SSE	10.6	27.9	25.47	81.2	87.1	94	81
17	91	75	82.8	69.2	0	18	82	51	64	0.00	28.70	29.95	SSE	10.5	28.3	27.32	81.2	87.1	94	81
18	89	75	81.5	70.9	0	17	86	54	71	0.00	28.74	29.98	SSE	8.9	21.9	20.91	81.2	86.8	92	82
19	86	71	78.5	69.9	0	14	92	60	76	0.00	28.71	29.95	SSE	8.5	20.0	20.31	80.5	85.2	90	80
20	89	69	77.8	67.7	0	14	98	44	74	0.53	28.65	29.90	SSE	5.3	18.8	21.26	79.7	82.2	86	79
21	92	68	78.2	63.2	0	15	91	34	63	0.00	28.67	29.92	N	6.2	23.9	23.90	79.1	80.4	89	74
22	88	65	74.7	65.1	0	11	98	49	73	0.93	28.61	29.85	ENE	7.0	65.5	18.57	78.0	78.7	84	74
23	89	67	77.0	69.8	0	13	97	55	80	0.62	28.57	29.81	E	6.8	22.8	22.33	77.9	78.7	85	73
24	83	66	71.9	67.2	0	9	98	68	85	1.08	28.59	29.83	SE	10.2	45.3	9.79	77.2	76.4	80	74
25	86	65	75.2	67.9	0	10	99	59	80	1.26	28.72	29.96	ESE	8.6	37.9	21.72	76.2	76.8	85	71
26	93	74	83.9	72.0	0	18	90	49	69	0.00	28.68	29.93	SSW	10.2	26.4	28.56	79.6	81.1	87	76
27	96	77	86.5	71.3	0	21	77	45	62	0.00	28.65	29.90	SSW	10.8	24.9	28.43	81.1	80.7	86	75
28	96	76	86.1	70.0	0	21	75	43	60	0.00	28.66	29.90	S	10.4	23.6	29.21	82.0	81.3	88	75
29	93	76	84.9	70.5	0	20	79	48	63	0.00	28.65	29.89	S	11.2	28.7	28.68	82.1	84.6	93	77
30	92	70	78.9	71.2	0	16	95	60	78	0.26	28.64	29.88	S	9.0	37.6	17.74	81.6	84.3	93	79
90* 71* 80.1* 68.5*				<- Monthly Averages ->				28.67* 29.91*		SSE*	9.0*	65.5*	23.66*	79.7*	82.5*	89*	77*			
Temperature - Highest: 96* Lowest: 58*				Degree Days - Total HDD: 0* Total CDD: 456*				Number of Days With: Tmax ≥ 90: 17* Rainfall ≥ 0.01 inch: 9* Tmax ≤ 32: 0* Rainfall ≥ 0.10 inch: 8* Tmin ≤ 32: 0* Avg Wind Speed ≥ 10 mph: 11* Tmin ≤ 0: 0* Max Wind Speed ≥ 30 mph: 6*												
Rainfall: Monthly Total: 6.55* in. Greatest 24 Hr: 1.65* in.				Humidity - Highest: 99* Lowest: 34*																

© 1993-2018 Oklahoma Climatological Survey and the Oklahoma Mesonet
Figure 18 June Mesonet Data

* Denotes incomplete record